0011

From:

Karl Houskeeper

To:

dshaver@coalsource.com

CC:

Angela Nance; Daron Haddock; Suzanne Steab

Date:

4/6/2009 2:28 PM

Subject:

March 2009 Inspection Reports

Attachments: Centennial March 2009.pdf; Crandall March 2009.pdf

Dave,

Attached are the March 2009 inspection reports for Centennial and Crandall.

Thanks,

Karl

Outgaing (0070019 (016003)

Œ



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:
Company	David Shaver Manager
OGM	April Abate Hydrologist
OGM	Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070019	
Inspection Type:	PARTIAL	
Inspection Date:	Wednesday, March 04, 2009	
Start Date/Time:	3/4/2009 8:30:00 AM	
End Date/Time:	3/4/2009 11:00:00 AM	
Last Inspection:	Wednesday, February 04, 2009	

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 37 deg. F. InspectionID Report Number: 1936

Types of Operations

Accepted by: jhelfric 3/11/2009

Oil, Gas & Mining JOHN R. BAZA

Division Director

Division of

Permitee: ANDALEX RESOURCES INC TOWER DIVISION

Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: CENTENNIAL MINE

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Curre	nt a	Acre	ages
-------	------	------	------

6,516.91	Total Permitted
47.19	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

✓ Federal ✓ Underground State ☐ Surface Loadout County Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. This condition is being met.

Date

Wednesday, March 04, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov Permit Number: C0070019

Inspection Continuation Sheet

Inspection Type: PARTIAL

Inspection Date: Wednesday, March 04, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	$\overline{\checkmark}$		~	
2.	Signs and Markers	V		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		V	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches	V	V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V	V		
8.	Noncoal Waste	V		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other			П	П

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Wednesday, March 04, 2009

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. This condition is being met.

2. Signs and Markers

The mine permit ID signs are located at the contact points of public access to the permit area.

4.a Hydrologic Balance: Diversions

Most of the diversions are still snow covered or have snow within their reaches.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The bottoms of the sediment ponds have ice and/or snow in them.

8. Noncoal Waste

Noncoal waste items present on pad adjacent to the bathhouse. The noncoal waste consists of insulation that came off the bottom of a portable trailer unit that was removed from the site and transferred to Lila Canyon.



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director Permitee: GENWAL RESOURCES INC

Operator: GENWAL RESOURCES INC

Site: CRANDALL CANYON MINE

Address: PO BOX 1077, PRICE UT 84501

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	6,235.80
Total Disturbed	27.15
Phase I	
Phase II	
Phase III	

JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:				
Company	David Shaver Manager			
OGM	Karl Houskeeper Environmental Scientist III			

Inspection Report

Permit Number:	C0150032
Inspection Type:	PARTIAL
Inspection Date:	Thursday, March 05, 2009
Start Date/Time:	3/5/2009 12:30:00 PM
End Date/Time:	3/5/2009 3:30:00 PM
Last Inspection:	Thursday, February 05, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 44 Deg. F. InspectionID Report Number: 1938

Accepted by: jhelfric

3/11/2009

		-	_
Types	of	Ope	rations

✓ Federal	✓ Underground
☐ State	☐ Surface
☐ County	☐ Loadout
☐ Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Mineral Ownership

ine	pecto	r's S	inna	furo:
II I Ə	necto	3 3	ıuna	ture.

Date

Thursday, March 05, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150032

Inspection Continuation Sheet

Inspection Type: PARTIAL

Inspection Date: Thursday, March 05, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.

 b. For PARTIAL inspections check only the elements evaluated.

 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	V		V	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	V	V		
6.	Disposal of Excess Spoil, Fills, Benches	V	V		
7.	Coal Mine Waste, Refuse Piles, Impoundments		· · · · · · · · · · · · · · · · · · ·		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	П	П	П	П

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Thursday, March 05, 2009

Page 3 of 3

2. Signs and Markers

The Mine ID sign is posted at the entrance to the permit area from the forest service road. The sign contains the name, permit ID #, address, and phone number of the operator. All other signs and markers observed during the inspection met the coal rules.

4.a Hydrologic Balance: Diversions

All of the diversions are snow covered. The majority of the mine site is still snow covered, except for the plowed road access.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Dave Shaver indicated that the sediment pond is still being pumped. The water elevation was at the bottom of the oil skimmer.

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2008 water monitoring is in the EDI website, but has not been uploaded by the Division. Water monitoring is current.